

Xgard Types 5, 6 and IR

Gas Detectors



Functional Safety Manual

Issue 1 March 2018

TABLE OF CONTENTS

1.	Introduction	2
2.	Safety Function	2
	Diagnostic Interval	
	Constraints	
	General Safety Information	
	Xgard Type 5 Additional Safety Information	
	Assessment Results	

1. Introduction

The following sections provide detail on the certification of **Xgard types 5**, **6 and IR** in accordance with the IEC 61508 Functional Safety standard. Information is given on the features considered in the safety case, maintenance requirements and data to enable **Xgard types 5**, **6 and IR** to be integrated into Safety Instrumented System (SIS).

2. Safety Function

To measure the concentration of flammable or toxic gas and indicate the measurement by means of a 4-20mA output. Failures in respect of the safety function will be detected by the hardware. They will be revealed as an output signal of less than 3mA. Alarm conditions will be revealed via a proportional analogue output signal in the range 4-20mA.

3. Diagnostic Interval

Diagnostic functions are continuously monitored, via analogue circuits, Xgard contains no microprocessors or software/firmware.

4. Constraints

Failure rates are constant. A proof test conducted every six months will identify all un-revealed failures. Repairs have a mean time to repair of 3 hours; this assumes that a trained and competent engineer and spare parts are available locally.

Sensors must be calibrated and replaced in accordance with the Xgard installation, operating and maintenance instructions.

Reliability assessment is a statistical process for applying historical failure data to proposed designs and configurations. It therefore provides a credible target/estimate of the likely reliability of equipment assuming manufacturing, design and operating conditions identical to those under which the data was collected. It is a valuable design review technique for comparing alternative designs, establishing order of magnitude performance targets and evaluating the potential effects of design changes. The actual predicted values cannot however be guaranteed as forecasting the precise number of field failures which will actually occur, since this depends on many factors outside the control of a predictive exercise.

Failure rates, for the purpose of this prediction, are assumed to be constant with time. Both early and wear-out related failures would decrease the reliability but are assumed to be removed by burnin and preventive replacement respectively.

5. General Safety Information

The following information must be observed during installation and use of Xgard gas detectors.

- Xgard gas detectors must be installed, operated and maintained in strict accordance with the
 instructions provided, warnings, label information, and within the environmental limitations
 stated.
- The lid on flameproof versions of Xgard must be kept tightly closed until power to the detector
 is isolated otherwise ignition of a flammable atmosphere can occur. Before removing the
 cover for maintenance or calibration purposes, ensure the surrounding atmosphere is free of
 flammable gases or vapours.
- The sinter (flame arrestor) should be inspected regularly, and replaced if it has become contaminated. A blocked sinter may prevent gas from reaching the sensor and represent an unrevealed failure.
- When performing maintenance on **Xgard**, ensure that the sensor retainer and junction box lid O-rings are present and in good condition to maintain the ingress protection of the product.
- **Xgard** detectors are designed to detect gases or vapours in air, and not inert or oxygen deficient atmospheres.
- Maintenance and calibration operations must only be performed by qualified service personnel.

- Only genuine Crowcon replacement parts must be used, substitute components may invalidate the certification and warranty of the detector.
- **Xgard** detectors must be protected from extreme vibration, and direct sunlight in hot environments as this may cause the temperature of the detector to rise above its specified limits and cause premature failure. A sunshade is available for Xgard.
- This equipment must not be used in a Carbon Disulphide atmosphere.
- Xgard Types 5, 6 and IR are certified for use in atmospheres that may contain flammable dusts. They will not however detect the presence of flammable dust, and the response of the gas sensor may be compromised by becoming blocked in a dusty environment. Xgard detectors should be inspected regularly if used in a dusty environment.
- Cable glands with a sealing compound must be used where Group IIC gases are likely to be present.

6. Xgard Type 5 Additional Safety Information

Xgard Type 5 utilises a 'pellistor' (catalytic bead) type sensor. Pellistors can suffer from loss of sensitivity when there is a presence of poisons or inhibitors such as silicones, sulphides, chlorine, lead or halogenated hydrocarbons. The sensor must be functionally tested regularly using test gas to verify correct operation in environments where such compounds may be present.

Crowcon use poison resistant pellistors to maximise the operational life of **Xgard**. In applications where such compounds are continuously present we recommend the use of Xgard IR, which is immune to such poisons and inhibitors.

The operational life of the pellistors depends on the application and the amount of gas to which the pellistor has been exposed. Under normal conditions (6 monthly calibration with periodic exposure to calibration gas) the life expectancy is 3-5 years.

7. Assessment Results

The following data represents a detector used in a simplex configuration. The FMEA analysis was subjected to the rigour of 100% simulated component failure testing. The following claims (particularly since they involve SIL 3) are thus highly robust. The FMEAs were adjusted to account for three types of input:

Xgard Type 5 (and Xsafe mA: Pellistor type sensor)

	Failure Rate ¹	PFD ²	SFF ³ %	S.I.L.
Failure to respond to high gas level	1	8.0 10 ⁻⁴	67	2
Spurious indication of a high gas level	0.05	•	ı	-
Total Failure Rate	1.1	ı	ı	-

Xgard Type 6 (Thermal Conductivity type sensor)

rigara Type e (Therma: Conductivity Type concer)						
	Failure Rate ¹	PFD ²	SFF ³ %	S.I.L.		
Failure to respond to high gas level	0.35	1.1 10 ⁻⁴	95	3		
Spurious indication of a high gas level	0.4	-	1	ı		
Total Failure Rate	1.1	-	-	-		

Xgard IR (Infrared type sensor)

Again in (illinated type sellsol)						
	Failure Rate ¹	PFD ²	SFF ³ %	S.I.L.		
Failure to respond to high gas level	0.7	1.3 10 ⁻⁴	95	2		
Spurious indication of a high gas level	0.05	-	ı	-		
Total Failure Rate	1.1	-	-	-		



© Crowcon Detection Instruments Ltd 2018

UK Office Crowcon Detection Instruments Ltd 172 Brook Drive, Milton Park, Abingdon Oxfordshire OX14 4SD Tel: +44 (0)1235 557709 Fax: +44 (0)1235 557749 Email: sales@crowcon.com Website: www.crowcon.com USA Office
Crowcon Detection
Instruments Ltd
1455 Jamike Ave, Suite 100
Erlanger
Kentucky 41018
Tel: +1 859 957 1039 or
1 800 527 6926
Fax: +1 859 957 1044
Email: salesus@crowcon.com
Website: www.crowcon.com

Crowcon Detection Instruments
Ltd
Vlambloem 129
3068JG
Rotterdam
Netherlands
Tel: +31 10 421 1232
Fax: +31 10 421 0542
Email: eu@crowcon.com
Website: www.crowcon.com

European Office

Singapore Office Crowcon Detection Instruments Ltd Block 194 Pandan Loop ~06-20 Pantech Industrial Complex Singapore 128383 Tel: +65 6745 2936 Fax: +65 6745 0467 Email: sales@crowcon.com.sg Website: www.crowcon.com China Office
Crowcon Detection Instruments Ltd
(Beijing)
Unit 316, Area 1, Tower B,
Chuangxin Building
12 Hongda North Road, Beijing
Economic Technological
Development Area
Beijing, China 100176
Tel: +86 10 6787 0335
Fax: +86 10 6787 4879
Email: saleschina@crowcon.cn
Website: www.crowcon.com

Crowcon reserves the right to change the design or specification of this product without notice.